

Tool Model: .7 MXT

Pressure/Torque Conversion Chart

PRESSURE IN: PSI	ft-lbs	TORQUE IN: KGM	NM	PRESSURE IN: BAR
1500	118	16	160	103
1600	126	17	171	110
1700	135	19	182	117
1800	143	20	194	124
1900	152	21	205	131
2000	160	22	217	138
2100	168	23	228	145
2200	176	24	239	152
2300	185	26	250	159
2400	193	27	262	165
2500	201	28	273	172
2600	209	29	283	179
2700	218	30	295	186
2800	226	31	306	193
2900	234	32	317	200
3000	242	33	328	207
3100	251	35	340	214
3200	259	36	351	221
3300	267	37	362	228
3400	275	38	373	234
3500	284	39	384	241
3600	292	40	396	248
3700	300	41	407	255
3800	308	43	418	262
3900	317	44	429	269
4000	325	45	441	276
4100	334	46	452	283
4200	342	47	464	290
4300	351	48	475	296
4400	359	50	487	303
4500	367	51	498	310
4600	375	52	508	317
4700	384	53	520	324
4800	392	54	531	331
4900	401	55	543	338
5000	409	57	555	345
5100	417	58	565	352
5200	425	59	576	358
5300	434	60	588	365
5400	442	61	599	372
5500	450	62	610	379

5600	458	63	621	386
5700	467	64	632	393
5800	475	66	644	400
5900	483	67	655	407
6000	491	68	666	414
6100	500	69	677	421
6200	508	70	689	427
6300	516	71	700	434
6400	524	72	710	441
6500	533	74	722	448
6600	541	75	733	455
6700	549	76	744	462
6800	557	77	755	469
6900	566	78	767	476
7000	574	79	778	483
7100	583	81	790	489
7200	591	82	801	496
7300	600	83	813	503
7400	608	84	824	510
7500	617	85	836	517
7600	625	86	847	524
7700	634	88	859	531
7800	642	89	870	538
7900	651	90	882	545
8000	659	91	893	552
8100	667	92	904	558
8200	675	93	915	565
8300	683	94	926	572
8400	691	96	937	579
8500	699	97	947	586
8600	706	98	957	593
8700	714	99	968	600
8800	722	100	979	607
8900	730	101	990	614
9000	738	102	1001	620
9100	747	103	1012	627
9200	755	104	1024	634
9300	764	106	1035	641
9400	772	107	1047	648
9500	780	108	1058	655
9600	788	109	1068	662
9700	797	110	1080	669
9800	805	111	1091	676
9900	814	112	1103	683
10000	822	114	1114	689